



# Ideal Low Maintenance Floor Finish

*Acabado Brilloso y Duradero*

## DESCRIPTION

A very durable floor finish that reduces the need for strip and recoat due to its mix-metal cross link technology. Responds very well to occasional high speed burnishing or spray buffing.

## DIRECTIONS

1. Strip floor entirely of old finish using a recommended floor stripper.
2. Apply finish using a clean finish mop. Apply up to 5 coats per application. Allow 30 - 45 minutes for finish to dry completely before recoating.
3. DO NOT apply more than 5 coats in 24 hours.
4. Maintain floor by dust mopping or sweeping as needed.
5. Clean floor using a neutral pH floor cleaner with damp mop or autoscrubber.
6. If desired, floor can be ultra high speed burnished using a medium aggressive pad.



## APPLICATIONS

### FOR LOW MAINTENANCE AREAS IN:

- > Schools and medical centers
- > Airports and retail
- > Offices

## SPECIFICATIONS

<b>Color</b> .....	White
<b>Fragrance</b> .....	Characteristic
<b>pH Range</b> .....	8.5 - 9.0
<b>Dilution</b> .....	RTU
<b>Density</b> .....	8.67

## PACKAGING

2/2.5 gallon                      MPL-1316-225P



5109 N National Dr. Knoxville TN 37914  
888.722.5508 | www.cleanfreak.com

MPL-1316-225P | 06-23-23

